


A—V,VP,VU—16(ø60)



	L1	L2
A—V,VP,VU—16(ø60)	50	78
	80	108
	100	128
	130	158
	150	178
	180	208
	200	228